PRINTED: 05/09/2019 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			LE CONSTRUCTION  01 - MAIN BUILDING 01		E SURVEY PLETED
					VI - III/III BOILDING VI		₹
		445108	B. WING			05/	06/2019
NAME OF F	PROVIDER OR SUPPLIER				STREET ADDRESS, CITY, STATE, ZIP CODE		
NHC HEA	ALTHCARE, MURFRE	ESBORO			20 N UNIVERSITY ST		
11110 1127	12(11071112) 111011111			I N	MURFREESBORO, TN 37130		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES  MUST BE PRECEDED BY FULL  SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
{K 000}	INITIAL COMMENT	гѕ	{K 0	00}			
	During the follow u 05/06/2019, all prev corrected.	p survey conducted on viously cited deficiencies were			इ.स.च		
					>		
LABORATORY	/ DIRECTOR'S OR PROVID	DER/SUPPLIER REPRESENTATIVE'S SIG	NATURE		TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID: TN7505

#### DEPARTMENT OF HEALTH AND HUMAN SERVICES

CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/02/2019 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  (X2) MULTIPLE CONSTRUCTION A BUILDING 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED	
445108 B. WING	03/20/2019	
NAME OF PROVIDER OR SUPPLIER  NHC HEALTHCARE, MURFREESBORO   (X4) ID  PREFIX  TAG  REGULATORY OR LSC IDENTIFYING INFORMATION)  STREET ADDRESS, CITY, STATE, ZIP  420 N UNIVERSITY ST  MURFREESBORO, TN 37130  PROVIDER'S PLAN O  PREFIX  (EACH CORRECTIVE AC  CROSS-REFERENCED TO  DEFICIENCY  DEFICIENCY  TAG  STREET ADDRESS, CITY, STATE, ZIP  420 N UNIVERSITY ST  MURFREESBORO, TN 37130  PROVIDER'S PLAN O  CROSS-REFERENCED TO  DEFICIENCY  DEFICIENCY  TAG  STREET ADDRESS, CITY, STATE, ZIP  420 N UNIVERSITY ST  MURFREESBORO, TN 37130	DF CORRECTION (X5) CTION SHOULD BE COMPLETION D THE APPROPRIATE DATE	2
Stories: 2 w/ partial basement Construction Type: II Constructed: 1958, 1970, 1976, 1982 Sprinkled: yes Census: 153 Certifled beds: 161  A Life Safety Code Federal Monitoring Survey was conducted by the Centers for Medicare & Medicaid Services (CMS) on 3/20/19 following a survey by the Tennessee Department of Health state survey agency on 2/25/19. At this survey, NHC Healthcare, Murfreesboro was found not in substantial compliance with the requirements for participation in Medicare/Medicaid at 42 CFR Subpart 43 48.77(0), and 483.70(b), Life Safety from Fire, and the related National Fire Protection Association (NFPA) publications, the 2012 edition of NFPA 101 Life Safety Code and Tentative Interim Amendments TIA 12-1, TIA 12-2, TIA 12-3, and TIA 12-4 and the 2012 edition of NFPA 99 Health Care Facilities Code and Tentative Interim Amendments TiA 12-2, TIA 12-3, TIA 12-4, TIA 12-5 and TIA 12-6. K 372 Subdivision of Building Spaces - Smoke Barrier Construction 2012 EXISTING Smoke barriers shall be constructed to a 1/2-hour fire resistance rating per 8.5. Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations in fully ducted HVAC systems where an approved sprinkler system is installed for smoke compartments adjacent to the smoke	ction is submitted r State and does not hission on the that the findings iency, or that the ty regarding the l are correctly	

Any deficiency structured ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing It is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

nined that

### DEPARTMENT OF HEALTH AND HUMAN SERVICES

CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/02/2019 FORM APPROVED OMB NO. 0938-0391

	DF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE A. BUILDING 0		RUCTION N BUILDING 01	(X3) DATE COMP	SURVEY LETED
		445108	B WING			03/	20/2019
	ROVIDER OR SUPPLIER  LTHCARE, MURFREESE		4 N	20 N UN	ADDRESS, CITY, STATE, ZIP CODE NIVERSITY ST EESBORO, TN 37130		(ME)
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES  Y MUST BE PRECEDED BY FULL  LSC IDENTIFYING INFORMATION)	ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 372	in REMARKS. This REQUIREMENT by: Based on observation facility failed to maint fire resistance of smoorequirements of: 2012 NFPA 101 Sect The deficiency affects barriers on the first flot Findings include: On 3/20/19 at 10:30 a at the corporate confordiameter hole in the world in the building which identified.	nical smoke control system  I is not met as evidenced on and document review, the ain the smoke and ½ hour oke barriers per the  ions 19.3.7.3, 8.5, 8.5.6  ed one of five smoke oor.  a.m., the smoke barrier wall erence room had a 1" wall. enance provided a plan of entified the wall as a smoke of Maintenance was present r in Training when the	K 372	3.	Maintenance audited smoke barrier wall on 3/21/19 with other issues identified.  Maintenance reviewed the Safety NFPA 101 (2012 Ed Sections 19.3.7.3, 8.5, 8.5. Smoke Barriers shall be constructed to a 1/2 hour firesistance rating per 8.5.  Ongoing monitors will be performed by Maintenance quarterly on preventive maintenance rounds. Any findings will be brought to the committee for follow up as indicated.	no Life ition) 6. re	3/21/19

Facility ID: TN7505

45th day / 70th 4-13-19 / 5-8-19 PRINTED: 02/28/2019 FORM APPROVED OMB NO. 0938-0391

(X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES COMPLETED **IDENTIFICATION NUMBER:** AND PLAN OF CORRECTION A. BUILDING 01 - MAIN BUILDING 01 445108 R. WING 02/25/2019 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER **420 N UNIVERSITY ST** NHC HEALTHCARE, MURFREESBORO MURFREESBORO, TN 37130 PROVIDER'S PLAN OF CORRECTION (X5) SUMMARY STATEMENT OF DEFICIENCIES (X4) ID COMPLETION (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** PRÉFIX CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG **DEFICIENCY**) K 000 K 000 INITIAL COMMENTS The plan of correction is submitted as required under State & Federal law and does not constitute an admission on the Stories: 1 part of the facility that the findings cited Construction Type: NFPA, II (111) are accurate, the findings constitute a No plans available on site deficiency, or that the scope & severity Constructed: 1950's-1960's regarding the deficiencies cited are Sprinklered: Yes correctly applied. Certified beds: 161 A Life Safety Code Survey was conducted by the State of Tennessee Department of Health Division of Health Licensure and Regulations Office of Health Care Facilities on 02/25/2019. During this Life Safety Survey, NHC Healthcare, Murfreesboro was found not in substantial compliance with the requirements for participation in Medicare/Medicaid with Title 42 CFR Subpart 483.70(a), The Rules of Tennessee Department of Health Board for Licensing Health Care Facilities Chapter 1200-08-06 Standards For Nursing Homes, and National Fire Protection Association (NFPA) 101 Life Safety (2012 Edition). \*Paperwork was provided showing the facility audited the AMANA PTAC units located throughout the facility and the repairs made. \*All sprinklers deficiencies shall be corrected in accordance with NFPA 13, Standards for the Installation of Sprinkler Systems (2010 Edition) and/or NFPA 25, Standards for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems (2011 Edition) The Maintenance Director removed the K 222 K 222 Egress Doors pad lock with a safety hasp on the outside SS=D | CFR(s): NFPA 101 of the door securing the oxygen storage tank room on 2/28/19.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Doors in a required means of egress shall not be

**Egress Doors** 

Administrator

Facility ID: TN7505

(X6) DATE

If continuation sheet Page 1 of 6

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

RECEIVED MAR 1 1 2019

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MUL A. BUILD		ATE SURVEY OMPLETED			
		445108	B. WING			02/2	5/2019
	PROVIDER OR SUPPLIER	ESBORO		42	REET ADDRESS, CITY, STATE, ZIP CODE 00 N UNIVERSITY ST URFREESBORO, TN 37130		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	400	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPIDE DEFICIENCY)	D BE	(X5) COMPLETION DATE
K 222	equipped with a latuse of a tool or key using one of the fol arrangements: CLINICAL NEEDS LOCKING Where special lock clinical security neonly one locking deeach door and provapid removal of oclocks; keying of all all times; or other sto the staff at all times; or other sto the staff at all times. SPECIAL NEEDS Where special lock safety needs of the Clinical or Security being met. In addit electrical locks that upon loss of power protected by a supsystem and the locked system and	ch or a lock that requires the from the egress side unless lowing special locking  OR SECURITY THREAT  Ing arrangements for the eds of the patient are used, evice shall be permitted on visions shall be made for the ecupants by: remote control of locks or keys carried by staff at euch reliable means available mes.  2.2.6, 19.2.2.2.5.1, 19.2.2.2.6  LOCKING ARRANGEMENTS ing arrangements for the expatient are used, all of the Locking requirements are ion, the locks must be a fail safely so as to release to the device; the building is ervised automatic sprinkler ked space is protected by a etection system (or is ead at an attended location pace); and both the sprinkler ems are arranged to unlock the ion.  2.2.5.2, TIA 12-4 is LOCKING	K 2	222	The Maintenance Director installed a door knob with a locking key system. chain was attached to the wall beside door with the key to unlock the door. Director of Maintenance will ensure compliance that all doors have a mean egress that is approved.	A the The	2/28/19

STATEMENT			(X2) MULTIPL A, BUILDING		(X3) DATE SURVEY COMPLETED	
		445108	B. WING		02/2	25/2019
	PROVIDER OR SUPPLIER ALTHCARE, MURFRE	ESBORO	4	TREET ADDRESS, CITY, STATE, ZIP CODE 20 N UNIVERSITY ST MURFREESBORO, TN 37130		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETION DATE
K 222	automatic sprinklet 18.2.2.24, 19.2.2.2 ACCESS-CONTRO ARRANGEMENTS Access-Controlled installed in accorda permitted. 18.2.2.24, 19.2.2.2 ELEVATOR LOBB ARRANGEMENTS Elevator lobby exit accordance with 7 door assemblies in by an approved, st detection system a automatic sprinkle 18.2.2.2.4, 19.2.2.2 This REQUIREME by: Based on an obse ensure that all doo egress shall not be lock that requires t egress side.  This deficiency aff any resident, staff enter the oxygen s The findings include Observation on 02 a padlock with a si door securing the NFPA 101, 19.2.2. The maintenance findings, which we	r system.  2.4  DLLED EGRESS LOCKING  Egress Door assemblies ance with 7.2.1.6.2 shall be  2.4  Y EXIT ACCESS LOCKING  access door locking in 2.1.6.3 shall be permitted on buildings protected throughout upervised automatic fire and an approved, supervised r system.  2.4  INT is not met as evidenced ervation, the facility failed to as in a required means of e equipped with a latch or a the use of a tool or key from the ects 1 smoke compartment and member, or visitors that may storage room.  de:  1/25/2019 at 6:17 AM, revealed afety hasp on the outside of the oxygen storage room.				

STATEMENT	OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA			CONSTRUCTION	(X3) DATE	SURVEY
AND PLAN C	F CORRECTION	IDENTIFICATION NUMBER:	A, BUILDII	NG 0	1 - MAIN BUILDING 01		
		445108	B, WING			02/2	5/2019
	PROVIDER OR SUPPLIER	ESBORO		42	REET ADDRESS, CITY, STATE, ZIP CODE 0 N UNIVERSITY ST URFREESBORO, TN 37130		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES  MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	<	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	) BE	(X5) COMPLETION DATE
K 353	CFR(s): NFPA 101  Sprinkler System - Automatic sprinkler inspected, tested, a with NFPA 25, Stantesting, and Mainta Protection Systems maintenance, inspendintal of the system service of the system service of the system.  Discovery of the system service of the system service of the system.  Provide in REMAR any non-required of system.  This REQUIREMED by:  Based on observation and any resident, so the findings included the system of the system of the system of the system.  The findings included the system of the syste	Maintenance and Testing and standpipe systems are and maintained in accordance dard for the Inspection, aining of Water-based Fire B. Records of system design, action and testing are cure location and readily beystem last checked  system test  Supply source  KS information on coverage for and NFPA 25 NT is not met as evidenced betion, the facility failed to brinkler system.  Sected all smoke compartments aff, or vistor in the building.  The compartments and 02/25/2019 between 5:06 bevealed no fire line back flow	K 2.		Johnson Controls was contacted by T Director of Maintenance. 3/5/19 the company Presented the service work On 3/7/19 the service work was signe the company to install 2 backflow preventers, one on each fire sprinkler riser #1 will have a new backflow inst vertically below the 6" alarm value. ri will have The backflow device installe horizontally with the main drain line reworked to make it fit. The backflow have butterfly shut off and will be do detector checks, as is required by Murfreesboro Water. The Maintenar Director will ensure compliance with sprinkler system.	order. d for system. alled ser #2 ed being ws will uble	4/13/19

CENTE	RS FOR MEDICARE	& MEDICAID SERVICES					0830-0381
STATEMENT	TEMENT OF DEFICIENCIES OPLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:				E CONSTRUCTION 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED	
		445108	B. WING			02/2	5/2019
NAME OF	PROVIDER OR SUPPLIER		-		TREET ADDRESS, CITY, STATE, ZIP CODE		
NHC HE	ALTHCARE, MURFRE	ESBORO			20 N UNIVERSITY ST IURFREESBORO, TN 37130		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 353	(2010 Edition), NFI The maintenance of findings, which were	age 4 PA 25, 13.6.2.1 (2011 Edition) director was present for the later acknowledged by the g the exit conference on	K	353	Tile 2 was sound our ron bottles were		
K 923 SS=D	Gas Equipment - CCFR(s): NFPA 101  Gas Equipment - CGreater than or equipment storage locations a ventilated in accord 5.1.3.3.3.  >300 but <3,000 cc Storage locations a within an enclosed limited- combustible gates outdoors) that gases are not store separated from consprinklered) or enconcombustible consprinklered) or enconcombustible consprinklered) or enconcombustible consprinklered in a single smoke cylinders available care areas with an or equal to 300 cult stored in an encloshandled with precay a precautionary signature in the sign incominimum "CAUTICSTORED WITHIN Storage is planned."	are outdoors in an enclosure or interior space of non- or e construction, with door (or at can be secured. Oxidizing ed with flammables, and are inbustibles by 20 feet (5 feet if closed in a cabinet of instruction having a minimum on rating. It is 300 cubic feet compartment, individual for immediate use in patient aggregate volume of less than bic feet are not required to be sure. Cylinders must be autions as specified in 11.6.2. In readable from 5 feet is on of a cylinder storage room, ludes the wording as a DN: OXIDIZING GAS(ES)	K	923	The 2 unsecured oxygen bottles were removed 2/25/19 immediately from the linen room by the Director of Mainter. The Director of Maintenance ensured oxygen bottles will be stored appropriately approp	nance. that	2/25/19

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			E CONSTRUCTION 01 - MAIN BUILDING 01	(X3) DATE COMP	SURVEY
		445108	B. WING			02/2	5/2019
	PROVIDER OR SUPPLIER ALTHCARE, MURFRE	ESBORO		42	TREET ADDRESS, CITY, STATE, ZIP CODE 20 N UNIVERSITY ST IURFREESBORO, TN 37130		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES  MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	DBE	(X5) COMPLETION DATE
K 923	Empty cylinders are cylinders. When faintegral pressure graconsidered empty is are marked to avoid in the open are produced in the open are produc	e segregated from full cility employs cylinders with auge, a threshold pressure is established. Empty cylinders diconfusion. Cylinders stored tected from weather.  3, 11.3.4, 11.6.5 (NFPA 99)  NT is not met as evidenced tions, the facility failed to en cylinders.  Toted 1 smoke compartment traff member, or visitor that in closet.  Extended to the clean linen of the clean line of the clean lin	KS	923			

PRINTED: 02/28/2019 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		ICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		TIPLE CONSTRUCTION	COM	(X3) DATE SURVEY COMPLETED	
		445108	B. WING			25/2019	
	PROVIDER OR SUPPLIER ALTHCARE, MURFRE	ESBORO		STREET ADDRESS, CITY, STATE, ZI 420 N UNIVERSITY ST MURFREESBORO, TN 37130	)		
(X4) ID PREFIX TAG	(FACH DEFICIENC)	NTEMENT OF DEFICIENCIES  Y MUST BE PRECEDED BY FULL  SC IDENTIFYING INFORMATION)	ID PREFI TAG		ON SHOULD BE HE APPROPRIATE	(X5) COMPLETION DATE	
E 000	Initial Comments  During the emerge conducted on 02/25 cited.	ency preparedness survey 5/2019, no deficiencies were	ΕC	000			
2					45		
		DERJOUPPLIER REPRESENTATIVE'S SI		TITLE		(X6) DATE	

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See Instructions.) Except for nursing homes, the findings stated above are disclosable 90 days of following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date of survey whether or not a plan of correction is provided. days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID: TN7505